


99ER-010

: HONDA TRX-350 RANCHER & 400 AT



REF	QTÉ/QTY	#pièce/part
1	2	04PL-408
2	1	04PL-409
3	1	HB3I8-16X2-1I2ZBG2
4	4	HB3I8-16X2ZBG2
5	5	HLN3/8-16ZBG2
6	1	04TU-167
7	1	HBM10x1,25x65ZBG8,8

2010-09-30

**Les Fabrication TJD inc.**147, chemin des Raymond Rivière-du-Loup (Québec), G5R 5X9
www.tjd.ca