


99XA-040

:HUB ADAPTER ASSEMBLY / ASSEMBLAGE
ADAPTEUR MOYEU

Liste des pièces / Part List

REF	#pièce/part	QTÉ/QTY	Couple / Torque
1	04AM-029	4	
2	00AM-035	4	
3	04AM-015	2	
4	HNWM10-1,25	16	66 N-m / 49 Lbs*feet
5	HSFCS3/8-16x1,25B2L	8	
6	HNW7116-20NF	16	75N-m / 55 Lbs*feet

2011-07-21



Les Fabrication TJD inc.

147, chemin des Raymond Rivière-du-Loup (Québec), G5R 5X9
www.tjd.ca