


99XA-049

:HUB ADAPTER ASSEMBLY / ASSEMBLAGE
ADAPTEUR MOYEU

Liste des pièces / Part List

REF	#pièce/part	QTÉ/QTY	Couple / Torque
1	04AM-034	4	
2	00AM-002	2	
3	04AM-003	2	
4	04AM-027	2	
5	HNWM10-1,25	16	66 N-m / 49 Lbs*feet
6	HSFCS3/8-16x1,25B2L	8	
7	HNW7I16-20NF	8	75N-m / 55 Lbs*feet

2011-07-21



Les Fabrication TJD inc.

147, chemin des Raymond Rivière-du-Loup (Québec), G5R 5X9
www.tjd.ca