


99XA-073

:HUB ADAPTER ASSEMBLY / ASSEMBLAGE
ADAPTEUR MOYEU

Liste des pièces / Part List

REF	#pièce/part	QTÉ/QTY	Couple / Torque
1	04AM-003	4	
2	00AM-002	2	
3	HNW7116-20NF	8	75N-m / 55 Lbs*feet
4	HNWM12X1,5	16	105 N-m / 77 Lbs*feet
5	04AM-034	4	

2013-01-22



Les Fabrication TJD inc.

147, chemin des Raymond Rivière-du-Loup (Québec), G5R 5X9
www.tjd.ca