


99XA-080

:HUB ADAPTER ASSEMBLY / ASSEMBLAGE
ADAPTEUR MOYEU

Liste des pièces / Part List

REF	#pièce/part	QTÉ/QTY	Couple / Torque
1	04AM-065	2	
2	HNW112-20NF	16	122 N-m / 90 Lbs*feet
3	HNW7116-20NF	8	75N-m / 55 Lbs*feet
4	04AM-058	4	
5	00AM-040	2	

2011-07-21



Les Fabrication TJD inc.

147, chemin des Raymond Rivière-du-Loup (Québec), G5R 5X9
www.tjd.ca